

Category <b>U</b>	<b>Technical</b>	Ref. No. E002/05	Page 1 of 1
Coverage <input type="checkbox"/> Distributor only <input checked="" type="checkbox"/> Please inform your dealers		Date Issued February 7, 2005	
Please convey this information to your <input type="checkbox"/> Director <input checked="" type="checkbox"/> General Manager <input checked="" type="checkbox"/> Warranty Dept. <input checked="" type="checkbox"/> Parts Dept. <input checked="" type="checkbox"/> Training Dept. <input checked="" type="checkbox"/> Field Rep.		Date Revised	
Applicable Models  Mazda3 (BK) with Auto A/C		Applicable Countries or Specifications  Worldwide (except North America)	


## Subject: Temperature Display Indicates Too High (Auto A/C)

### DESCRIPTION

Some customers may complain that the auto A/C's temperature display indicates too high (60 – 90 degrees).

When both of the audio power switch and tape/MD play switch are held pressed for approximately two seconds, the temperature display automatically changes from Celsius to Fahrenheit by itself.

This is a normal function of the auto A/C and not a problem.



### ACTION TO BE TAKEN

When you encounter a customer complaint on this concern, first confirm with the customer how s/he operates the audio switches.

If the customer uses the same operation as mentioned above, change the temperature display back to Celsius by performing the same operation (holding both of the audio power switch and tape/MD play switch pressed for approximately two seconds), and then explain the customer this is not a problem.

Fumihiko Aoyama  
General Manager  
Technical Service Department  
Mazda Motor Corporation